

Confidential

Internal Report

Product and Application

Product Name : Daikacoat 2000
Facility Name : Kiln SP ID Fan

The situation before applying

The material was built up on the fun and vibration of the fun often increased. The kiln needed to be stopped one or two time in 6 month to clean up the coating on the fun.

Result after application of the product

There was no extreme increase of the vibration and it only gradually increased but it had not reached beyond allowable level so that the kiln has not stopped within 6 month. Also, the record of the vibration indicates that the coating was sometimes dropped off by itself without any enforcement.

